

STEINER INDUSTRIES[®] 5801 NORTH TRIPP AVENUE, CHICAGO, ILLINOIS 60646-6013

MATERIAL SAFETY DATA SHEET

#37900

SECTION I – PRODUCTION IDENTIFICATION

RED SILICONE COATED FIBERGLASS

Chemical Name and Synonyms: N/A Chemical Family: N/A

SECTION II – HAZARD INGREDIENTS/IDENTITY INFORMATION

Fibrous Glass

10 mg/m³ of air For fiber diameters Less than 7 microns

SECTION III – PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINTN/AVAPOR PRESSURE (MM HG)N/AVAPOR DENSITY (AIR=1)N/A

SPECIFIC GRAVITY (H20=1) MELTING POINT EVAPORATION RATE (BUTYL ACETATE=1) gible

1000 F

N/A

2.4

SOLUBILITY IN WATER APPEARANCE AND ODOR Negligible Reddish Orange Coated Fabric/No odor

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (METHOD USED)

250 F by TOC FLAMMABLE LIMIT LEL: N/A

UEL: N/A

EXTINGUISHING MEDIA SPECIAL FIRE FIGHTING PROCEDURES UNUSUAL FIRE AND EXPLOSION HAZARDS Water, carbon dioxide, dry chemical None known None known

SECTION V – REACTIVITY DATA

STABILITYStableINCOMPATIBILITYStrong oxidizing agentsHAZARDOUS DECOMPOSITION OR BYPRODUCTSCarbon dioxide, carbon monoxideHAZARDOUS POLYMERIZATIONWill not occur, None known

STEINER INDUSTRIES RED SILICONE COATED FIBERGLASS #37900

SECTION VI – HEALTH HAZARD DATA

ROUTE(S) OF ENTRY This material will not enter the body during normal use INHALATION N/A SKIN N/A INGESTION N/A HEALTH HAZARDS (ACUTE AND CHRONIC) None known CARCINOGENICITY This product is not known to be a carcinogen NTP No I.A.R.C. MONOGRAPHS No **OSHA REGULATED** No SIGNS AND SYMPTOMS OF EXPOSURE None known MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE None known EMERGENCY AND FIRST AID PROCEDURES Wash with soap and water after handling

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Material is a solidWASTE DISPOSAL METHODBurial in a federal, state, or local approved landfillPRECAUTIONS TO BE TAKEN IN HANDLING AND STORINGUse adequate material handling

OTHER PRECAUTIONS None known

SECTION VIII - CONTROL MEASURES

RESPIRATORY PROTECTION (SPECIFY TYPE) None needed VENTILATION LOCAL EXHAUST None needed None needed MECHANICAL Special None needed OTHER None needed **PROTECTIVE GLOVES** None needed EYE PROTECTION None needed OTHER PROTECTIVE CLOTHING OR EQUIPMENT None needed WORK HYGIENIC PRACTICES Wash with soap and water after handling

equipment

FOR PROPRIETARY REASONS WE HAVE OMITTED THE MANUFACTURERS NAME.